

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problems Mailbox.**

DC Bus

Z

Vcc

30

Vb

64

HIN

LIN

Buffer

Driver

DSH/VFH

54

19

A~18

Motor

34

32

22

84

VS

62

A~16

VFH

Driver

DSL/VFL

52

oVcc

12

VEL

8.5

24

82


VSS


C20

10

Fig. 1

Prior Art





PRIOR ART

FIG. 3




Fig. 4




Fig. 5




FIG. 6